F-3-68 Frederick Cronise Farmstead Lewistown vicinity Private

The Frederick Cronise Farmstead is centered on a circa 1836-1845 log dwelling with brick veneer and double entries in its south elevation and the associated outbuildings which include a rare surviving separate bake oven and a combination blacksmith shop and summer kitchen/slave quarters, both of about the same date as the house. A circa 1850 brick springhouse is also part of the domestic group. The agricultural buildings include a frame bank barn of about 1830-1850, a log hog barn built about the same period, two frame sheds built during the last quarter of the 19th century, one for wagons, with corn cribs on the sides, and the other a carriage shed. The farmstead buildings are in deteriorated condition, but are important because of the internal planning of the complex and for the log and brick technology of the structures. The bake oven may be one of possibly five of the separate structure type in the northern part of Frederick County.

F-3-68 Frederick Cronise Farmstead Lewistown Frederick County

HISTORIC CONTEXT:

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA

Geographic Organization: Piedmont

(Harford, Baltimore, Carroll, Frederick, Howard, Montgomery

Counties, and Baltimore City)

Chronological/Development Period:

Agricultural-Industrial Transition, A.D. 1815-1870

Prehistoric/Historic Period Themes:

Architecture, Landscape Architecture and Community Planning

Resource Type:

Category: Building

Historic Environment: Rural

Historic Function and Use:

Domestic/single dwelling/residence

Domestic/secondary structure/other dependencies Agriculture/subsistence/animal facility/barn

Known Design Source: None

Maryland Historical Trust State Historic Sites Inventory Form

M32 P28

Survey No. F-3-68

Magi No.

DOE __yes ^x_no

1. Nan	ne (indicate p	referred name)		
historic Fr	rederick Cronise Fa	rmstead		
and/or common				
2. Loc			· · · · · · · · · · · · · · · · · · ·	
street & numbe	r 11700 Whates L	ane		not for publication
city, town I	Lewistown	_x_ vicinity of	congressional district	6th
state M	Maryland	county	Frederick	
3. Clas	ssification			
Category district ×_ building(s) structure site object	Ownership public private both Public Acquisition in process being considered not applicable	Status X occupied unoccupied work in progress Accessible X yes: restricted yes: unrestricted no	Present Use _x_ agriculture commercial educational entertainment government industrial military	museum park x private residence religious scientific transportation other:
4. Owr	ner of Prope	erty (give names a	nd mailing addresse	s of <u>all</u> owners)
name Rob	pert D. Leatherman			
street & number	r 11920 Auburn Ro	ad	telephone n	o.:
city, town Thu	ırmont	state	and zip code Md.	21788
5. Loc	ation of Leg	gal Description	on	
courthouse, reg	jistry of deeds, etc.	rederick County Cour	thouse	liber ⁴⁸⁹
street & number	r 100 W. Patrick	Street		folio ³⁷⁹
city, town	Frederick		state	Md.
6. Rep	resentation	in Existing	Historical Surv	veys
i ltle Ant	chony James Survey	of Frederick County	F-20-6	
date 196	58 - 70		federalX stat	te county loca
∌pository for s	survey records Maryl	and SHPO		
city, town	Crownsville		state	Md. 21032

7. Description

Survey No. F-3-68

Condition excellent good	deteriorated ruins	Check one unaltered _X altered	Check one X original si moved	te date of move	
X fair	unexposed				

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

CONTRIBUTING RESOURCE COUNT: 9

The Frederick Cronise Farmstead is an agricultural complex centered on a circa 1836-1845 log dwelling with late 19th century brick veneer and its associated domestic and agricultural outbuildings, which include a separate brick bake oven, a brick springhouse, a brick building which housed a blacksmith shop, a summer kitchen, and slave quarters, all of which, except the springhouse of about 1850, date from about the same period as the dwelling. The agricultural buildings include a frame bank barn on a stone foundation which probably dates from about 1840-1850, a frame wagon shed/corn crib and a frame carriage shed which probably date from about 1875-1900, and a log outbuilding, possibly a hog barn, which may be of the same period as the barn. The complex also includes a terra cotta tile silo of the early 20th century and several non-contributing modern period agricultural buildings, among which is a dated 1950 concrete block dairy barn and milk house. The Cronise Farmstead is located on the east side of U.S. 15 at the end of a lane which parallels the highway extending south from Spahr's Quarry Road, about two miles north of Lewistown, Frederick County, Maryland. The principal elevation of the house faces south and the access drive enters the complex from the north.

The dwelling has two stories and an irregular bay arrangement on the south The first story has four bays and the second story has three. Double entries are located in the inner bays and the exterior covering of stretcher bor. brick veneer is missing over the entrances, leaving the outline of an entry porch which has been removed, revealing the log structure of the house. Both entries are boarded, but a four-light transom is visible above one of the doorways. The windows are 6/6 with wood lintels and sills. The roof is covered with corrugated metal and standing seam metal on the north slope and the cornice is boxed. Interior end chimneys rise at each gable end. On the west elevation are two bays with 6/6 windows and 2/2 attic windows flanking the chimney. The east elevation has a single bay at the rear of the main section with 6/6 sash. A two-story rear wing extends from the northwest corner of the main section. It has 5:1 American bond and gauged arches, suggesting that it may have load-bearing brick walls and was added to the original log section in the second quarter of the 19th century. The wing has both 6/6 and 2/2 sash and a composition and pressed metal roof with a boxed cornice. Two chimneys are located in the wing. On the east elevation of the wing is a two-story integral porch which is enclosed on the first story and covered with german siding.

The interior of the house is in generally poor condition as a result of neglect over many years. In the first floor east parlor is a simple mantel of the period about 1830. Most walls are covered with wall paper or modern paneling. Much of the wall paper, especially on the second floor, is separated from the wall surface. Doors are generally 6 and 8 panels. In the southeast corner of the main section is a winding staircase and the rear wing also has a corner stair. Floors appear to be original.

(Continued on seperate sheet)

Period preh 1400 1500 1600 1700 X 1800 1900	-1499 archeology-historic -1599 agriculture -1699 architecture -1799 art -1899 commerce		literature military music t philosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	dates C. 1836-1845	Builder/Architect		
check:	Applicable Criteria: _A and/or Applicable Exception:		EFG	
	Level of Significance:	_nationalstate	<u>x</u> local	
Prepare	both a summary paragraph	of significance and a	a general statement c	f history and

Survey No. F-3-68

8. Significance

Prepare both a summary paragraph of significance and a general statement of history and support.

The Frederick Cronise Farmstead is a fair example of farmstead planning and architecture of the second quarter of the 19th century. The bake oven is one of possibly five known to exist in the northern section of the county (estimate made by Anthony James in an earlier survey of the late 1960's). The combination blacksmith shop and summer kitchen is also unusual among the known outbuildings surviving in other farmsteads of the period, the blacksmith shop usually being closer to the agricultural buildings. The log dwelling may have been built by about 1836 when Frederick Cronise acquired the property. The property was resurveyed in 1841 as "Cronise's Prospect". By 1854, his son Jacob Cronise had inherited the property and probably added the springhouse about that time. The appearance and plan of the farmstead, excluding the modern period agricultural buildings, was determined during the Cronise ownership, but in 1868, Daniel Leatherman purchased the property and it has remained in the Leatherman family to the present. The non-contributing dairy barn is one of the structures added to the complex in 1950 by the Leatherman family.

Major Bibliographical References Survey No. F-3-68 Bond, Isaac, Map of Frederick County, 1858 Land Records of Frederick County Titus, C.O., Atlas of Frederick County, 1873 Williams, T.J.C., and Folger McKinsey. History of Frederick County, 1910. Baltimore Regional Publishing Co., 1979, p. 1054. **Geographical Data** 5 acres Acreage of nominated property 1:24000 Quadrangle name <u>Catoctin Furnace</u>, Md. Quadrangle scale UTM References do NOT complete UTM references Easting Zone **Easting** Northing Zone Verbal boundary description and justification Approximately 5 acres centered on the dwelling on Tax Map 32, Parcel 28 List all states and counties for properties overlapping state or county boundaries state code county code code code county state Form Prepared By name/title Janet L. Davis, Historic Sites Surveyor date September 1992 organization Frederick County Planning & Zoning Dept. street & number 12 E. Church Street telephone 696-2958 Md. 21701 Frederick state city or town The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated

Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

MARYLAND HISTORICAL TRUST DHCP/DHCD 100 COMMUNITY PLACE CROWNSVILLE, MD 21032-2023 -514-7600

Frederick Cronise Farmstead Frederick County

7.1 Description (Continued)

Domestic outbuildings:

Bake oven: The separate bake oven is a rare surviving feature of the farmstead, although it is in deteriorated condition. It formerly had a frame gable roof protecting the domed top, but the roof is missing and the oven top shows the effects of exposure in missing bricks and plaster. On the south elevation is an iron door. Part of the wall structure in which it is set has fallen away, exposing the interior of the oven. The north side of the oven has the firebox and flue, both of which are in poor condition. The bake oven may date from about the late 1830's to the mid-1840's and was probably built at the same time as the house.

Springhouse: The square plan brick springhouse is located south of the house, while the other domestic outbuildings are located in a line extending east from the rear wing of the house. The springhouse has 5:1 brick walls and a hipped shingle roof with a central cupola. A vertical board door is located in the east elevation, and louvred windows are in the south and north elevations. The design of the building and its materials suggest that it dates from about 1850. The spring itself is covered by a modern concrete enclosure just north of the springhouse.

Blacksmith shop and summer kitchen: The brick combination building is located east of the bake oven. It has one story with two rooms. A loft above the east room is believed by the owner to have been slave quarters. The lower space has a large stone fireplace opening and an exterior stone and brick chimney is located on the east gable end. The west room apparently served as a blacksmith shop, with a forge enclosure still in place in the northeast corner. Both rooms are accessed through vertical board doors in the south elevation. The window openings are altered in a horizontal shape on this elevation and the north elevation has small 2/2 windows in each room. The gable ends are covered with board and batten siding and the roof is corrugated metal.

Agricultural outbuildings:

Bank barn: The frame bank barn has a stone foundation and vertical siding. It appears to have been built about 1840-1850, with a late 19th century addition of a wagon shed and corn crib on the west gable end. The roof of the barn is covered with corrugated metal. A corrugated metal loafing shed is located at the east end. The south elevation has louvred vents and the stall level is enclosed with horizontal flush boards. Near the ramp on the north elevation is a terra cotta silo with a frame gable top.

Wagon shed/corn crib: The frame wagon shed with corn cribs was built probably in the last quarter of the 19th century. Located north of the bank barn, it has vertical siding, which is greatly deteriorated. The roof is standing seam metal. The shed is linked to the carriage shed by an open-sided shed for equipment.


Carriage shed: The carriage shed, also built in the period 1875-1900, is located west of the wagon shed and is linked by the open-sided shed, essentially just a roofing of the open space between the two frame buildings. The carriage shed has


7.2 Description (Continued)


vertical board doors and a gable standing seam metal roof. Fragments of decorative bargeboard trim survive on the shed, which is also in deteriorated condition.

Log barn: The log barn is located east of the wagon shed and is not in use. The log structure is open, without chinking, and the roof is missing. Vertical siding apparently once covered the barn, but is only partly in place. A low opening on the south elevation suggests that it may have been used as a hog barn. Its date is probably about 1840-50.

	11700 M	bates Lane			i de la companya de		
of which have	LIBER/FC 0		GRANTOR		ORIGINAL TRACTS	COST	DATI
	4 8 9/379	Robert D. Leather	Marshal L., K	Dorothy	1420-		
No.	29 Dec 50	man	m. William Margaret E.	Longher			
	ш.		11-2-		<u> </u>	=	
	11110 202/40	D. A. C. Alany	Cheirs of Buth				
	12 abs 10	Luther E. Houry	Harry \$. and				
	rauporo.	Leatherman	F. Leathern	un			
LW					montion dono Home	# 85/2	1+84 1818
	mill Record	Levelle E. Harry	Doniel Lear	therman	mentions Home Garm 4 mountain land 17 a.	go o speece	(try 1868 Onder for
	WBC 2/143	J. + Orestes J.			Springhield farm to 3 daughters al \$ 8000		Jacob Cronise
	10 Mar 02	Leatherman			scedigmin - m		to be featherman
	CM 1/578	0 - 14 -1	ann M. + ga	of Cours	"Cronise's Prospect".	\$19,54.73	for Jacob Course
		Daniel Leathern	Const. In grant		- releven Cromise.		acquisition Jacob Cronise liven 1827, sold in
	13 apr/868				22 apr 1841 1020. 190 4650 =	159Q.	leen 1827, Sold in
			H	P.	"Cronise's Prayect"		
	ES 10/167	Jacob Cronise	Frederick 2 The	ma com	102+9		GH1/242
	11 326-1854						APK 3/632
					111000	# CR/2 50	
	HS 4/125	Frederick Cronise	John McPhe	erson,	"Springfield"	\$5,862.50	
1	30 Dec 1836		strusted for s	ale of	mentions mansions		
			Brien, dec.	10	divelling Lause on we side of road to Brin	Jeernase &	on Lewistour
1							77
1							3
							83
. 13							
3							








Frederick Cronise Farmstead Frederick County C.O. Titus, Atlas of Frederick County, 1873

lagerstouen F.D. 1873





F-3-68 Frederick Cronise Formstead Frederick County Proto Jovet Covis September 1992 Neg-loc. And. SHPO Crownsville Ind. South Elevation



Frederick Cranics Farmstead Frenchick County Photo: Tanet Lays Near lee: 11d. SUID From WIL, M.



Frederick Cromse Formstead

Frederick County

Photo. Jonet Cavis

September 1922

Neg-loe: 1962 SHPO, Crownswille, 1966

Bake oven, south elevation



Frederick Cronise Formstead
Frederick County
Photo: Jonet Davis
September 1992
Nea. loc. Md. SHFO. Crownsville. Md

Bake over north elevation



Frederick County Photo Janet Davis September 1992 Nea. loc. Md. SHFO, Crownsville, MA Block Shilth Shop & Summer Kitchen, South elevation 5/9



F-3-68 Frederick Cronse Formstead Frederick County Photo: Jonet Davis September 1992 Neg-loc. Md-SHPO Crownsville, Md Springhoose, northeast corner view 6/1







4-3-68 Frederick Cronise Formstead Frederick County Photo: Jonet Dows Soptember 1992 Neg- loc. Md. SHPO, Crownsville, Md. Los born, south elevation 7/9